

Laptop & Data Projector (NEC LT-265) Setup Instructions

1. Plug in the power cables for projector and laptop
2. Connect one end of the VGA cable to **Computer 1 IN** on the data projector (Figure 2)

Projector cables





Figure 2



3. Connect the other end of the VGA cable to the **blue video port** on the laptop

4. Turn on projector main power switch by pushing the rocker switch located on the back of the projector: 0=off, I=on (Figure 3)

Figure 3



5. Turn on the projector - press and hold the **ON/STAND BY** button on the projector or the **ON** button on the remote control for a minimum of 2 seconds (Figures 4-5)




Figure 4




Figure 5

6. Turn on the computer

7. Press the Computer 1 button on the projector remote control (Figure 6)
 - ❖ If no image displays, push the **Fn** key and the **LCD/CRT** key on the laptop simultaneously. Wait a moment. Repeat the process to get and image on both the screen and the laptop.

Figure 6



8. Push up and hold the **ADJUSTABLE TILT FOOT BUTTON** on the front of the projector to extend the adjustable tilt foot up and Focus the projector using the focus knob on front of the projector (Figure 7)

9. Adjusting the image size and the focus (Figure 7)
 - ❖ Use the **ZOOM LEVER** to adjust the image size on the screen
 - ❖ Use the **FOCUS RING** to focus

Figure 7



Tilt Foot

Focus & Zoom

10. To turn off projector, press and hold the **ON/STAND BY** button on the projector or the **OFF** button on the remote control for a minimum of 2 seconds *Wait for fan to stop before unplugging power cord*