



Overhead Projectors

User Instructions




Overhead
Projectors



Materials

- Transparency film or writing roll



- Wet/Erase transparency pens



Operating Equipment

- Plug in and Power on
- If light does not come on
 - check for spare bulb
 - Some models have 2 bulbs, Push lever to switch to spare bulb
 - Contact A/V Technician
- Move O/H to optimal location
- Place transparency on lighted surface

